

Wind Farm CASALDUNI

Inspector	Ing. Matteo Canevello
Attendants to the inspection	Ing. Raffaele Petrucciolo
Inspection Date	05.04.23

Definitions

Category of Defect	Description of Category	Results of Inspection
Minor Defect	defect to be remedied	NO finding
Major Defect	major defect to be remedied on short term	NO findings
Critical defect	safety critical defect, immediate action to be taken	NO findings
n.a.	not applicable in this type of turbine	

Findings

No.	Category	Description of Defect	Defect cat.
	Punch		Minor Defect
		Component damaged during the transportation, to be restored before the erection.	

Site Visit Report Wind Farm CASALDUNI

FICHTNER

General Information on wind farm

1	Wind Farm Information	
1.1	Wind Farm	PARCO EOLICO CASALDUNI
1.2	Location	CASALSUNI/PONTELANDOLFO, Benevento, Campania, Italy
1.3	Status	In construction
1.4	Commissioned	-

2	Wind Turbine Information	
2.1	Manufacturer	Siemens Gamesa Renewable Energy Wind
2.2	Type / Capacity	G132 / 3.645 MW
2.3	Wind farm capacity	34.65 MW
2.4	Rotor diameter	132 m
2.5	Hub height	114 m

Inspection

3	Access to the	site	
3.1	Roads	Roads in good condition	No relevant defect observed during the inspection

4 WTG08

4	Crane platform	Works completed, restoration works to be done after the WTG erection completion	No relevant defect observed during the inspection
4	Foundation	Foundation piles successfully tested and backfill completed	No relevant defect observed during the inspection

4 WTG



No relevant defect observed during the inspection





Erection activities ongoing

5	WTG09		
5	Crane platform	Works completed; restoration works to be done after the WTG erection completion	No relevant defect observed during the inspection
5	Foundation	Foundation piles successfully tested and backfill completed	No relevant defect observed during the inspection
	WTG		No relevant defect observed during the inspection



Blades installation



Erection activities ongoing

Minor Defect Major Defect Critical Defect

defect to be remedied major defect to be remedied on short term safety critical defect, immediate action to be taken not applicable in this type of turbine

6 WTG10		
6 Crane platform	Works completed, restoration works to be done after the WTG erection completion	No relevant defect observed during the inspection
6 Foundation	Foundation piles successfully tested and backfill completed	No relevant defect observed during the inspection
6 WTG	Tower installed	No relevant defect observed during the inspection

7	WTG11		
7	Crane platform	Works completed, restoration works to be done after the WTG erection completion	No relevant defect observed during the inspection
7	Foundation	Foundation piles successfully tested and backfill completed	No relevant defect observed during the inspection
7	WTG		No relevant defect observed during the inspection
		Erection expected in the next days	

8	WTG13		
8.1	Crane platform	Works completed, restoration works to be done after the WTG erection completion	No relevant defect observed during the inspection
8.2	Foundation	Foundation piles successfully tested and backfill completed	No relevant defect observed during the inspection

8.3 WTG



No relevant defect observed during the inspection

Erection expected in the next days

9	WTG14		
9	Crane platform	works ongoing	No relevant defect observed during the inspection
9	Foundation	Foundation poured, backfill works ongoing	No relevant defect observed during the inspection
9	WTG	No installation activities started	

12

WTG18 No relevant defect Crane observed platform during the inspection Finishing works ongoing relevant No defect Foundation observed during the inspection Backfill works ongoing No installation activities started 1 WTG

11	WTG3		
11.1	Crane platform	works ongoing	No relevant defect observed during the inspection
11.2	Foundation	Foundation poured, backfill works ongoing	No relevant defect observed during the inspection
11.3	WTG	No installation activities started	

1	WTG04		
1	Crane platform	works ongoing	No relevant defect observed during the inspection
1	Foundation	Foundation poured	
1	WTG	No installation activities started	

13	WTG05		
13.1	Crane platform	works ongoing	No relevant defect observed during the inspection
13.2	Foundation	Foundation poured, backfill works ongoing	No relevant defect observed during the inspection
13.3	WTG	No installation activities started	

Underground MV line

13.4 Trenches and cable laying



No relevant defect observed during the inspection

Works ongoing, the delivery of the cable will follow the work progress

Electrical Substation

13.5 Civil works

No relevant defect observed during the inspection

Minor civil works expected to be completed soon

13.6 Cabins

Switchgears expected to be delivered and installed by mid-April 2023 No relevant defect observed during the inspection

Minor Defect Major Defect Critical Defect n.a. defect to be remedied major defect to be remedied on short term safety critical defect, immediate action to be taken not applicable in this type of turbine