

Wind Farm CASALDUNI

Inspector	Ing. Matteo Canevello,
Attendants to the inspection	Dott. Paolo Sanmartino
Inspection Date	09.03.23

Definitions

Category of Defect	Description of Category	Results of Inspection
Minor Defect	defect to be remedied	NO finding
Major Defect	major defect to be remedied on short term	NO findings
Critical defect	safety critical defect, immediate action to be taken	NO findings
n.a.	not applicable in this type of turbine	

Findings

No.	Category	Description of Defect	Defect cat.

Site Visit Report Wind Farm CASALDUNI

FICHTNER

General Information on wind farm

1	Wind Farm Information	
1.1	Wind Farm	PARCO EOLICO CASALDUNI
1.2	Location	CASALSUNI/PONTELANDOLFO, Benevento, Campania, Italy
1.3	Status	In construction
1.4	Commissioned	-

2	Wind Turbine Information	
2.1	Manufacturer	Siemens Gamesa Renewable Energy Wind
2.2	Type / Capacity	G132 / 3.645 MW
2.3	Wind farm capacity	34.65 MW
2.4	Rotor diameter	132 m
2.5	Hub height	114 m

Inspection

inspeci	11011		
3	Access to the site		
3.1	Roads	Roads in good condition	No relevant defect raised during the inspection
4	WTG08		
4.1	Crane platform	Crane on site ready to start the erection activities	No relevant defect raised during the inspection
4.2	Foundation	State on site ready to start the decition activities	No
		Foundation piles successfully tested and backfill completed, waiting for the WTG erection	relevant defect raised during

Minor Defect Major Defect Critical Defect n.a. defect to be remedied major defect to be remedied on short term safety critical defect, immediate action to be taken not applicable in this type of turbine

WING FAITH CASALDONI		ГІСПІ	INEU
			the inspection
4.3	WTG	Yet to be erected	
5	WTG09		
5.1	Crane platform	Works completed, waiting for the WTG erection	No relevant defect raised during the inspection
5.2	Foundation	Foundation piles successfully tested and backfill completed, waiting for the WTG erection	No relevant defect raised during the inspection
5.3	WTG	Erection expected in the next weeks	
6	WTG10		
6.1	Crane platform	Works completed, waiting for the WTG erection	No relevant defect raised during the inspection
6.2	Foundation	Foundation piles successfully tested and backfill completed, waiting for the WTG erection	No relevant defect raised during the inspection
6.3	WTG	Erection expected in the next weeks	
7	WTG11		
7.1	Crane platform	Works completed, waiting for the WTG erection	No relevant defect raised during the inspection
7.2	Foundation	Foundation piles successfully tested and backfill completed, waiting for the WTG erection	No relevant defect raised during the inspection
	WTG		



defect to be remedied major defect to be remedied on short term safety critical defect, immediate action to be taken not applicable in this type of turbine

8	WTG13		
8.1	Crane platform	Works ongoing	No relevant defect raised during the inspection
8.2	Foundation	backfill works completed, final layer to be laid	No relevant defect raised during the inspection
8.3	WTG	Yet to be erected	

9	WTG14		
9.1	Crane platform	works ongoing	No relevant defect raised during the inspection
9.2	Foundation	Foundation poured	No relevant defect raised during the inspection
9.3	WTG	Yet to be erected	

10	WTG18		
10.1	Crane platform	works ongoing	No relevant defect raised during the inspection
10.2	Foundation	backfill works ongoing	No relevant defect raised during the inspection
10.3	WTG	Yet to be erected	

11	WTG3		
11.1	Crane platform	Preliminary works ongoing	No relevant defect raised during the inspection
11.2	Foundation	Preliminary works ongoing, expected to be poured in the second half of March	
11.3	WTG	Yet to be erected	
12	WTG04		
12.1	Crane platform	works ongoing	No relevant defect raised during the inspection

Foundation		
WTG	Yet to be erected	
WTG05		
Crane platform	works ongoing	No relevant defect raised during the inspection
Foundation	Preliminary works ongoing	
WTG	Yet to be erected	
	WTG05 Crane platform Foundation	Foundation Preliminary works ongoing, expected to be poured by mid-March WTG Yet to be erected WTG05 Crane platform works ongoing Preliminary works ongoing

Minor Defect Major Defect Critical Defect n.a. defect to be remedied major defect to be remedied on short term safety critical defect, immediate action to be taken not applicable in this type of turbine

14	Underground MV line		
14.1	Trenches and cable laying	Works ongoing, the delivery of the cable will follow the work progress	
15	Electrical Substation		
15.1	Civil works	Minor civil works expected to be completed soon	No relevant defect raised during the inspection
15.2	Cabins	Switchgears expected to be delivered and installed by mid-April	No relevant defect raised during the inspection